


















ASTI 20 / RUMBA 20




						 J14 8	 O7 2	 L9 2	
				 M3 8	 B2 4	 T9 9	 F10 6	 P14 6	
				 L2 10	 P5 10	 P1 26	 R2 8	 J12 4	
				 U1 4	 O1 1	 I 2	 T4 2		
 E 16	 H 4	 P7 13	 D2 20	 C 20	 A 16	 L 14	 S1 4	 J3 8	 G 4

1


310/27mm  I	 T4	$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 15/12 \text{ mm}$  C	L=20mm  D2	$\varnothing 6,3 \times 20 \text{ mm}$  M3	 F10	$\varnothing 4.0 \times 25 \text{ mm}$  P14	$\varnothing 4.0 \times 16 \text{ mm}$  P1
2	2	16	20	20	8	6	6	13
 T9	$\varnothing 20/8 \text{ mm}$  J14							
9	8							




1




2









3






4











 P7	 L2	 L
13	10	10



φ4.0x16mm  P1	13
--	-----------








7








†10x50mm		†3.5x13mm
		
O7	L9	P5
2	2	2

8



$\varnothing 6 \times 42 \text{mm}$		$L=128 \text{mm}$	$\varnothing 4.0 \times 30 \text{mm}$	
				
B2	O1	S1	R2	L
4	1	2	4	4





x2





9

$H=0$	$\varnothing 35/0 \text{mm}$	$\varnothing 3.5 \times 13 \text{mm}$
		
H	G	P5
4	4	8



x2



$\varnothing 5/16\text{mm}$  J3 8	 J12 4	$L=128\text{mm}$  S1 2	$\varnothing 4.0 \times 30\text{mm}$  R2 4	$M4 \times 9\text{mm}$  U1 4	 E 16
---	---	--	--	--	--

